

RECORD OF
COMMUNICATION☐ Phone Call☐ Discussion☒ Field Trip☐ Conference☐ Other (speSFUND RECORDS CTR
2166-00307TO: Josh Workman
JW 1/24

FROM: Al Novak

DATE: 1/23/85

SUBJECT: Bendix Electrodynamics Division No. Hollywood
Tank removal

FILE NO: 91605 3098

SUMMARY OF COMMUNICATION:

Bendix had 4 u.g tanks removed from this facility on 1/22/85. The 4 tanks were each 1000 gal, steel, installed 1942 and contained leaded and unleaded gasoline, kerosene and Stoddard solvent. I visited the site to observe the removal and sampling. None of the tanks appeared to be leaking and there were no petroleum odors apparent in the soil. There was a septic odor present which could have been caused by a leaking sewer line but none was uncovered during the excavation (which was ~ 12' x 24' x 9' deep). Two soil samples were taken from under each tank for analysis. One will be analyzed and the other will be archived for possible future testing. A total of eight samples were taken and 4 will be analyzed.

Contractor - W.W. Irwin.

Consultant - Leighton & Assoc. Mimi Maki,

LAFD inspector also present.

CONCLUSIONS, ACTION TAKEN OR REQUIRED:

INFORMATION COPIES TO: